




## 注意事項

- 警告
  - 腐食性のある物質が含まれている雰囲気や気体の中では、使用しないでください。
  - 引火性、爆発性のあるガス、液体、雰囲気の中では使用しないでください。本製品は防爆構造ではありませんので、火災、爆発の原因となる恐れがあります。
  - 使用温度範囲を超える発熱のある使い方はしないでください。センサーの故障の原因となる危険性があります。
  - 配線は、必ず電源を切ってから行ってください。また、配線時にはリード線の色、端子番号などを確認し、出力端子と電源端子、common端子を短絡させないでください。短絡した場合、センサーの故障の原因となる危険性があります。
- 注意
  - 電源は、安定した直流電源をご使用ください。
  - 出力端子や電源端子に接続する(リレー、バルブなど)には、サージ電圧吸収回路を入れてください。また、電源が定格を超えるような使い勝手は避けてください。
  - スイッチング電源などのユニット電源を使用する際は、FG端子を接地してください。
  - 出力端子と他の端子を絶対に短絡させないようにご注意ください。
  - センサー取扱時は継手部本体とセンサーケース間にコジリ、引張り等の負荷を与えないでください。また、配線はセンサー本体に引張荷重の掛からない様に、余裕のある長さで行ってください。継手部本体とセンサーケース接続部の破損につながります。
  - ノイズなどの印加されるような配線、または使い勝手をした場合、故障の原因となる可能性があります。
  - リード線には、強い引張力や極端な曲げを与えないでください。断線やコネクタ部の破損の原因となります。
  - 設定ボタンは、先端が鋭利なもので押さないでください。設定ボタンの破損につながります。
  - 設定ボタンには過度な力を掛けないでください。ボタン又は製品自体の破損につながります。
  - DINレール固定を行う際は、35mm幅のDINレールをご使用ください。
  - DINレール固定を使用する場合には、市販のDINレール固定具を製品の両側面に取付けて固定を確実に行ってください。過度の振動、衝撃によりDINレールから製品が外れる可能性があります。
  - DINレール用リリースレバーに過度の荷重をかけないでください。リリースレバーの破損につながります。特にDINレールにセンサーを取付けた状態でチューブの取付け、取外しを行う際は、リリースレバーに荷重がかからぬよう本体を手で押さえて行ってください。
  - LED 表面ディスプレイは、出荷時に保護フィルムが貼られています。必要に応じて剥がしてご使用ください。
  - 止めピンを抜くことによりカートリッジ継手の番脱が可能ですが、使用時には止めピンが確実に挿入されていることを確認してください。
  - 水漏、油漏、塵埃のかかる所では使用しないでください。防漏、防塵構造ではありませんので、作動不良の原因となる可能性があります。
  - 本センサーと同じ電源に他の機器が接続されている場合、一側(COM)が遮断した状態で負荷の動作テスト用スイッチ等により SW 出力端子を一極と短絡させると、スイッチ出力回路に逆電流が流れ、センサーが破損します。このような回路でご使用になる場合は、一側の電源線上か、SW 出力線上に逆流防止のダイオードを下図の向きで設置してください。



## 仕様

品名	VUS8-□S	VUS8-□SR
一般仕様	使用流体 圧力検出方法 使用温度範囲 保存温度範囲 使用湿度範囲 耐振動 耐衝撃 保護構造	空気(非腐食性) 拡散半導体圧力スイッチ 0 ~ 50℃ -20 ~ 70℃(大気圧、湿度65%RH以下) 35 ~ 85%RH(結露無きこと) 100ms/s <sup>2</sup> 150ms/s <sup>2</sup> IEC規格 IP40 相当
圧力レンジ	使用圧力範囲 耐圧	-100kPa ~ 0kPa 200kPa
電源	供給電源 消費電流 圧力表示素子 表示回数 監視機能 特殊機能	DC12 ~ 24V ±10% (リップル:P-P含む) 30mA以下(全点灯、2点出力無負荷ON時) 符号付2桁、7セグメント赤色LED(文字高: 4.5mm) 4 回 / 秒 圧力オーバー表示、点滅表示 ボタン操作により有効/無効を選択 ボタン操作により有効/無効を選択
表示	圧力表示倍率 圧力表示範囲 (ゲージ圧力表示) 表示分解能 表示精度 温度特性 ゼロ点調整 出力点数 出力方式 スイッチ容量 残留電圧 出力動作 圧力設定範囲 動作表示 温度特性 繰返し精度 応答性 応差設定 過負荷保護回路	×1(kPa) ×0.75 ×0.01 ×0.145 -99 ~ 0(x1) -75 ~ 0(×0.75) -99 ~ .00(×0.01) -14 ~ 0(×0.145) ±1%F.S. ±1count ±3%F.S. (0 ~ 50℃、基準温度 25℃) ゼロアジャストモードにて調整 2 点出力(SW1、SW2) NPN オープンコレクタ DC30V 80mA以下 セパレートモード、ウインドコンパレータモード 出力 ON 時: LED 点灯 (SW1: 赤 / SW2: 緑) ±5%F.S. (0 ~ 50℃、基準温度 25℃) 約2、25、250ms (選択) ヒステリシス設定により可変、0 ~ 30counts (VUS8-□-SRの場合、30kPa相当) 無し

## 使用方法

### 配線接続方法




### パネル面各部の名称




この度は、ピスコ製品をお買い上げいただき誠にありがとうございます。  
本製品をお客様に安心してお使いいただくために、本取扱説明書を必ずお読みください。又、本書は大切に保管していただきますようお願い申し上げます。

## 取扱説明書

### ■起動時(電源投入時)のLED表示




### ■パネル操作手順フロー



### パネル操作手順


- 注意
  - 設定ボタンは、先端が鋭利な物で押さないでください。設定ボタンの破損につながります。
  - 設定ボタンには過度な力を掛けないでください。ボタン又は製品自体の破損につながります。

#### ①選択モード操作手順




- 注意
  - 選択モードに入っている状態で、5秒以上無操作状態が続くと、自動的に動作モードに戻ります。選択モードから先の各設定モードに入った後は、5秒以上無操作でも動作モードに戻りません。

#### ②表示モード on/off (表示設定モード)




- 注意
  - 4. 表示モードが解除されている時、動作モードにて無操作状態が10秒以上続く、と表示を消灯します。この時の表示は下図の通りとなります。また、SW が出力されている場合は、(S1)赤色LED、(S2)緑色LEDが点灯します。

#### ③表示倍率、スイッチ出力動作の設定手順(初期設定モード)



表示倍率を設定する場合は、左側の桁を点滅させ、▼ボタンで表示倍率Noを選択します。▼ボタンをワンタッチする毎に、1→3→4→5→1の順で切り替わります。※表示倍率Noにつきましては、下表「表示倍率No」をご確認ください。



表示倍率、スイッチ出力動作の選択が終了した後、▼と▲ボタンを同時に1秒以上押し、設定を確定します。動作モードに戻り、圧力表示を開始します。※この確定の操作が行われるまで(設定中)は、選択モードに入る以前の設定にてスイッチ出力が動作します。確定操作の後、はじめて新設定が有効となります。


### 表示倍率No

表示倍率No	表示倍率	圧力レンジ
1	×1 (kPa/MPa)	S: 負圧タイプ SR: 連成圧タイプ
3	×0.75	-99 ~ 0
4	×0.01	-75 ~ 0
5	×0.145	-99 ~ .00
		-14 ~ 0

- 注意
  - 7. [パネル操作手順] ③ \* 表示倍率、スイッチ出力動作の設定手順<初期設定モード> \* に従い、設定してください。
  - 8. 工場出荷時の設定は、表示倍率No1の "1倍" に設定されています。
  - 9. 圧力レンジ SR: 連成圧タイプは、表示倍率No1の "1倍" のみの表示となります。また、SR: 連成圧タイプでは、負圧 (≤0kPa): kPa表示、正圧 (0kPa<): MPa表示となります。


### スイッチ出力動作 No / 動作図

出力モード	セパレート	ウインドコンパレータ	セパレート	ウインドコンパレータ
動作	HI	LO	HI	LO
1	○		○	
2	○		○	
3		○		○
4		○		○
5		○		○
6		○		○
7		○		○
8		○		○
圧力設定(動作点)	設定1	下限: 設定1 上限: 設定2	設定2	下限: 設定1 上限: 設定2




- 注意
  - 10. [パネル操作手順] ③ \* 表示倍率、スイッチ出力動作の設定手順<初期設定モード> \* に従い、設定してください。
  - 11. 工場出荷時の設定は、圧力レンジ S: 負圧タイプの場合、スイッチ出力動作 No4 \* セパレートモード (SW1 LO 動作 / SW2 LO 動作) \*、圧力レンジ SR: 連成圧タイプの場合、スイッチ出力動作 No1 \* セパレートモード (SW1 HI 動作 / SW2 HI 動作) \* に設定されています。

#### ④SW動作圧力値、応差、フィルター(応答性)設定手順<スイッチ設定モード>




- 注意
  - 12.SW動作圧力値、応差設定は \* [パネル操作手順] ③スイッチ出力動作の設定\*を行った後に行ってください。特に、セパレートモードからウインドコンパレータモードに出力動作の変更を行うと、設定されていた応差は全て「0」となります。また、SW1の動作圧力値はSW2の動作圧力値に変更されます。この為、必ずスイッチ出力動作設定の後、SW動作圧力値、応差値を設定してください。

#### ⑤ゼロ点補正手順<ゼロアジャストモード>



- 注意
  - 13. 表示圧力範囲±10%以上の圧力が圧力ポートに掛かっている場合、監視機能により "E2" が表示されます。この時、(▲)ボタンを押すとE2が解除されます。(※動作モードに戻ります。)

### ⑥パネルロック設定手順



### エラー表示について

エラー表示	内容	対処
E0	当社での調査を必要とします。	最寄りの販売店へお問い合わせください。
E2	ゼロ点調整時に圧力が加わっています。(残圧など)	(▲)ボタンを押してE2を解除します。→動作モードに戻ります。圧力ポートの圧力を開放し、もう一度ゼロ点調整をしてください。
E3	設定データが失われた可能性があります。	電源を再投入し、初期設定及びスイッチ設定をご確認ください。正常復帰しない場合は、最寄りの販売店へお問い合わせください。
E3.4	検出範囲(110%FS)を超えています。	通常動作しています。印加圧力を定格圧力以下に設定してください。

### チューブ着脱方法


- 警告
  - 1. チューブ取り外しの際は、必ずエアを止め、残圧を排気してから行ってください。
- 注意
  - 1. DINレールにセンサーを取付けた状態でチューブの取付、取外しを行う際は、リリースレバーに荷重がかからぬよう本体を手で押さえて行ってください。
- ①. チューブの装着: 8mm幅LED表示付圧力センサーは、チューブをチューブエンドまで差し込むだけでロックが固定。弾性材料リリースがチューブの外周をシールします。装着の際は、弊社総合カタログ、継手の共通注意事項「2 チューブ装着上の注意」を参考に装着してください。
- ②. チューブの取外し: チューブを取外す場合、開放リングを押すことによりロック爪が開き、チューブを抜くことができます。取外しの際は、必ずエアを止め、残圧を排気してから行ってください。

### 固定方法

- 注意
  - 1. 製品に過大な振動や衝撃を与えないでください。製品の破損、性能低下の原因となる可能性があります。
  - 2. センサー取扱時は継手部本体とセンサーケース間にコジリ、引張り等の負荷を与えないでください。また、配線はセンサー本体に引張荷重の掛からない様に、余裕のある長さで行ってください。継手部本体とセンサーケース接続部の破損につながります。
  - 3. ネジにより製品を固定する際はM3ネジにより推奨締付トルク0.3~0.5N・mで確実に締付けを行ってください。
  - 4. DINレール固定を行う際は、35mm幅のDINレールをご使用ください。
  - 5. DINレール固定を行う際は、市販のDINレール固定具を製品の両側面に取付けて固定を行ってください。
  - 6. 製品をDINレールに取り付ける際、及び取り外す際は、リリースレバーに過度な荷重をかけないでください。リリースレバーの破損につながります。
  - 7. LED表示画面は押さないでください。表示画面の破損につながる恐れがあります。


#### ①ネジ、及びブラケットにて固定する場合

- 樹脂本体の取付け穴(2個)若しくは、ブラケットの取付け穴(2個)を利用し、M3ネジで締付け固定します。また、その時の推奨締付けトルクは、0.3-0.5N・mとなります。推奨締付けトルク範囲外で締付けた場合には、製品の脱落や破損の原因となる可能性があります。



#### ② DINレールに取り付ける場合


- 1. 取り付け時  
固定フックをDINレールの片側に掛け、図の矢印の位置を指て押し取り付けます。  
※ LED表示画面は押さないでください。表示画面の破損につながる恐れがあります。
- 2. 取り外し時  
リリースレバーを図の方向へ引き上げて取り外します。  
※ 過度に引き上げるとリリースレバーの破損につながる恐れがありますのでご注意ください。



### カートリッジ継手の交換方法

- 注意
  - 1. カートリッジ継手を本体に装着する際には、Oリングにゴミ、毛羽などの付着物が無い事を必ず確認してください。また、Oリング、及び本体内部に傷を付けないでください。真空回路の漏れによる性能低下の原因となります。
  - 2. ピン引抜時、及び装着時はセンサーケース部に過度な力を掛けないでください。下図の指定位置を保持し、作業を行ってください。
  - 3. カートリッジ継手の交換後は止めピンが確実に挿入されていることを確認してください。

カートリッジ継手の交換は、止めピンをマイナスドライバーなどで引き抜き、カートリッジ継手を取り外します。



### 圧力単位換算表

圧力単位	kPa	cmHg	bar	psi
1	1	7.50 × 10 <sup>-1</sup>	1.00 × 10 <sup>-2</sup>	1.45 × 10 <sup>-1</sup>
1.33	1.33	1	1.33 × 10 <sup>-2</sup>	1.93 × 10 <sup>-1</sup>
1.000 × 10 <sup>4</sup>	1.000 × 10 <sup>4</sup>	7.50 × 10 <sup>1</sup>	1	1.45 × 10 <sup>2</sup>
6.90	6.90	5.17	6.90 × 10 <sup>-2</sup>	1

※ その他詳細につきましては、下記までお問い合わせください。



# PISCO®

## 8mm Width Pressure Sensor with LED display

# VUS8 Series

## User's Manual

HIR0040-00


### ⚠ Safety Instructions

#### ● Warnings

- This product must not be used in the ambience or gas where corrosive substance is dissolved.
- Avoid using this product in the inflammable explosive gas, liquid or ambience. This product is not designed to be explosion-proof and may cause fire or explosion.
- This product shall not be used in the temperature higher than the specified range thus generating heat. To do so can cause damage to the sensor.
- Make sure that the power supply is turned off when wiring. Make sure of the colors of the lead wire and terminal numbers so that the output terminal and the power supply terminal or the common terminal shall not be shorted out. If this happens, it can cause damage to the sensor.

#### ● Cautions

- Make sure that the power is supplied from the stable DC power source.
- Make sure to provide the surge voltage absorption circuit in the relay or valves that connect to the output or power supply terminals. Also, make sure to use the rated power source.
- When using the unit current such as the switching current, make sure that the FG terminal is grounded.
- The output terminal shall never be short circuited with other terminal(s).
- When handling the sensor, do not apply twist or pull to the connection part of Tube Fitting and sensor case. When wiring, do not allow tension load to the main body and make some allowance for cable length. Doing so may cause breaking of the connection part.
- An applied or impressed wiring (such as with a noise) may cause function failure.
- The lead wire shall not be subjected to strong pull or extreme bending. Doing so may cause breaking of the wire or breakdown of the connector.
- Avoid pressing the setting buttons with a sharp pointed tool. It may break the buttons.
- Do not apply excessive force to the setting buttons. Applying excessive force may damage the buttons or main body.
- When affixing the sensor via DIN railing, make sure that the width of the DIN rail to be used is 35mm wide.
- If there is still vibration or shock to the sensor after the sensor is affixed using the DIN railing, add extra DIN railings (available in the market) on both sides of the sensor to further stabilize the sensor. The sensor can come off the railing from the excessive vibration or shock.
- Be careful not to overload the release lever of the DIN railing. Excessive load may break the lever. When the tube is connected or disconnected on the condition that the sensor is affixed to the DIN railings particularly, hold the main body by hand not to overload the release lever.
- The LED display is covered with a protective film at shipment. Please remove it as necessary.
- The cartridge fitting can be attached and removed by pulling out the lock pins, but make sure the lock pins are surely installed on the operation.
- Do not use the sensor in locations where it can be exposed to water drops, oil drops, dust, etc. It is neither drip-proof nor dust-proof, so that trouble may result.
- When the sensor and other electric equipments are connected to the same power supply, and the SW output terminal is short-circuited with minus (-) terminal by a load operation test switch etc. on the condition that minus (-) terminal (COM) is shut off, the backward current flows to switch output circuit and the sensor will be broken.
- In the case used under the circuit, please install backward prevent diodes on the minus (-) terminal power line or SW output line as shown below.




### Specifications

Model	VUS8-□-S	VUS8-□-SR
General specification	Fluid admitted Method of pressure detection Operational temperature range Storage temperature range Operational humidity range Vibration resistance Impact resistance Protective structure	
	Air (non-corrosive) Diffusion semiconductor pressure switch 0 ~ 50°C -20 ~ 70°C (Atmospheric pressure: Humidity: under 65%RH) 35 ~ 85%RH (no condensation) 100m/s² 150m/s² IEC standard IP40 equiv.	
Pressure range	Service pressure range Proof pressure	-100kPa ~ 0kPa 200kPa
Power supply source	DC12 ~ 24V ±10% (ripples included) Consumption current Pressure display elemental device Frequency of display Monitor function Special function	
	Max. 30mA (with all the lights on, no load on the two output points) Signed 2-digits, 7-segments red LED (with character height of 4.5mm) 4 times/sec. Warning for over-pressure: Blinking display Select to enable or disable the function by button setting. Select to enable or disable the function by button setting.	
Display	Pressure indication magnification Pressure display area Display resolution	×1(kPa) ×0.75 ×0.01 ×0.145 -99 ~ 0(x1) -75 ~ 0(x0.75) -99 ~ .00(x0.01) -14 ~ 0(x0.145) 1(x1) 1(x0.75) 0.01(x0.01) 1(x0.145)
Switch output	Output points Output method Switch capacity Residual voltage Output mode Pressure setting range Operational indication Thermal characteristics Repetitiveness Response setting Setting of differential response Protective circuit against overload	NPN open collector Max. DC30V, 80mA Separate mode, Window comparator mode -99 ~ 0 counts (at kPa) LED light up (SW1: red; SW2: green) at the main power output ON ±5%F.S. (0 ~ 50°C, reference temperature 25°C) ±0.3%F.S. Choose from approx. 2, 25 or 250 (msec.) Changeable by the hysteresis setting; 0-30 counts (equivalent to 30kPa in the case of VUS8-□-SR) None

### Operation Method


#### ■ Wiring connection




#### ■ Description of each section of panel



#### ■ LED display at start-up



#### ■ Panel operation




### Panel operation procedures

#### ● Caution

- Avoid pressing the setting buttons with a sharp pointed tool. It may break the buttons.
- Do not apply excessive force to the setting buttons. Applying excessive force may damage the buttons or main body.

#### ① Select mode operation procedure




Each mode shows: dl shows display mode.  
ln shows initial setting mode.  
SS shows switch setting mode.  
OA shows zero-point adjust mode.

#### ● Caution

- If there is no operation at least 5 seconds in select mode, it returns to action mode automatically. If the operation mode is proceeded to respective setting mode after select mode, it does not return to action mode even there is no operation at least 5 seconds.


#### ② Setting and canceling of lights-out mode (Display mode)



"on" or "of" is displayed.  
"on" and "of" are alternately displayed when ▲ button is pressed each time.  
"of" sets the light-out mode and "on" cancel the light-out mode.


#### ● Caution

- While setting lights-out mode, if there is no operation at least 10 seconds in action mode, the display lights out. The light-out display is as follows. When SW is output, the (SW1) red LED and (SW2) green LED light up.




- If temporal pressure display is required while lights-out mode is selected, press the DOWN button or the UP button one time, the pressure value is displayed and turned off if there is no operation at least 10 seconds.
- The ex-factory value is set at display mode "on".

#### ③ Setting procedures of magnification level and switch output operation (Initial setting mode)



For setting magnification level, blink left digit and choose magnification level No by ▼ button. Pressing the ▼ button one time changes the display in the order of 1 → 2 → 3 → 4 → 5 → 1.  
\*Please refer to the following chart for magnification level No.



After selecting magnification level and switch output operation, press the DOWN button and the UP button simultaneously for at least 1 second and set the mode. Return to action mode and start pressure display.

\*Until above operation is set (during setting operation), the switch output functions in the previous setting value before select mode. After the operation is set, new setting value is effective.

#### Display Mode Setting



Magnification level No	Magnification level	Pressure range	
		S : Negative Pressure Type	SR : Compound Pressure Type
1	×1 (kPa/MPa)	-99 ~ 0	-99 ~ .30
3	×0.75	-75 ~ 0	-
4	×0.01	-99 ~ .00	-
5	×0.145	-14 ~ 0	-

#### ● Caution

- Follow ③ Setting procedures of magnification level and switch output operation <Initial setting mode> for the setting.
- The ex-factory magnification level is set at "×1".
- The magnification level of SR : compound pressure type is only "×1" and compound pressure displays in negative pressure (≤ 0kPa) kPa, positive pressure (0kPa <) MPa.

#### Switch output operating No / Operating chart

Output Mode Action	SW1				SW2			
	Separate	Window comparator	Separate	Window comparator	Separate	Window comparator	Separate	Window comparator
1	HI	LO	A	B	HI	LO	A	B
2								
3								
4								
5								
6								
7								
8								
pressure setting (operating point)	Setting 1	Bottom limit: Setting 1 Ceiling: Setting 2	Setting 2	Bottom limit: Setting 1 Ceiling: Setting 2	Setting 2	Bottom limit: Setting 1 Ceiling: Setting 2	Setting 2	Bottom limit: Setting 1 Ceiling: Setting 2






P1 : Setting 1, P2 : Setting 2, H : Switch hysteresis

#### ● Caution


- Follow ③ Setting procedures of magnification level and switch output operation <Initial setting mode> for the setting.
- The ex-factory value for pressure range S : Negative type is set at switch output operation No 4 "Separate mode (SW1 LO operation/SW2 LO operation)" and for pressure range SR : Compound pressure type is set at switch output operation No 1 "Separate mode (SW1 HI operation/SW2 HI operation)".

#### ④ Setting procedures of SW operating pressure value, differential response and filter (response) (Switch setting mode)




- Please set SW operation pressure and differential value after setting switch output operation in ③ Panel operation procedures. Especially, if there is a case that the output operation is change from separate mode to window comparator mode, the all setting value of differential response becomes "0". And, the SW1 output operation value is changed to SW2 output operation value. Therefore, make sure to set SW operation pressure value and differential response value after setting switch output operation setting.

#### ⑤ Setting procedure of zero point adjustment (zero-point adjust mode)



- In the event of residual pressure being 10% F.S. or more, the error indication "E2" will appear due to monitoring function. Pressing ▲ button cancels E2 and return to action mode. Again make sure that the residual pressure in the pressure port is released and conduct zero point adjustment.

#### ⑥ Setting procedure of panel lock



### Error indication

Error No.	Error indicated	How to deal with error
E0	A PISCO representative will need to see the unit.	Please consult the nearest PISCO office.
E2	Pressure was applied at the time of "0" point adjustment. (Residual pressure, etc.)	Cancel E2 by pressing ▲ button and return to action mode. Release the residual pressure in the pressure port, and then conduct zero point adjustment.
E3	Some of the set data may have been lost.	Re-activate the power source, and check the initial setting and switch setting. In case it does not return to the normal condition, consult nearest PISCO office.
E3.4	The pressure is beyond the set range (110%FS).	Normal operation Set supply pressure below rated pressure.


### How to fit and release Tubing

#### ● Warning

- Before releasing the tube, make sure the air is stopped and residual pressure is exhausted.

#### ● Caution

- When the tube is fitted or released on the condition that the sensor is installed on DIN rail, hold main body by hand not to overload the release lever.




### How to fix 8mm width Pressure sensor with LED display

#### ● Caution

- Do not apply excessive vibration or shock to the sensor. Using it in such conditions can lead to breakage and performance deterioration.
- When handling the sensor, do not apply twist or pull to the connection part of Tube Fitting and sensor case. When wiring, do not allow tension load to the main body and make some allowance for cable length. Doing so may cause breaking of the connection part.
- Use M3 screws to fix the unit by the recommended tightening torque of 0.3-0.5N · m.
- When affixing this sensor via DIN rail, make sure that the width of the DIN rail to be used is 35mm wide.
- When affixing this sensor via DIN rail, apply DIN rail bracket (available in the market) on both sides of the sensor.
- Be careful not overload the release lever when the sensor is mounted on or removed from the DIN rail. Excessive load may break the lever.
- Do not press the LED display. Doing so may cause breakage.


#### ① How to fix the sensor with screws or bracket

- Use M3 screws to fasten in the two (2) tightening holes on the plastic main body or on the bracket. The recommended torque is 0.3 to 0.5N·m. Fastening the screws with the torque out of this range can cause fall or damage of the product.



#### ② How to fix the sensor with DIN rail

- Mounting  
Hook the fixing hook on the one side of DIN rail and press the main body for fixing.  
\*Do not press LED display. Doing so may cause breakage.
- Dismounting  
Pull up the release lever to the direction shown below and remove the sensor.  
\*Pulling up the release lever excessively may break the lever.




### How to replace cartridge fitting

#### ● Caution

- When installing cartridge fitting, be sure to confirm that no dust, fluff, etc. are sticking to the O-ring. Do not damage O-ring and inner parts of main body. Damaging these parts may lead to decrease in performance due to air leakage in the vacuum circuit.
- Do not apply excessive force to the sensor case when taking out and putting in the lock pin. Please keep the designated position in the picture below and conduct operation.
- After replacement of the cartridge fitting, make sure the lock pins are surely installed.

Pull out the lock pins using flat-tip screwdriver or other appropriate tool and replace the cartridge fitting.



### Pressure unit conversion chart

Pressure unit	kPa	cmHg	bar	psi
Pressure	1	7.50 × 10 <sup>-1</sup>	1.00 × 10 <sup>-2</sup>	1.45 × 10 <sup>-1</sup>
	1.33	1	1.33 × 10 <sup>-2</sup>	1.93 × 10 <sup>-1</sup>
	1.000 × 10 <sup>2</sup>	7.50 × 10 <sup>1</sup>	1	1.45 × 10 <sup>1</sup>
	6.90	5.17	6.90 × 10 <sup>-2</sup>	1

\* Please make inquiry about other details to the following.

### NIHON PISCO CO.Ltd.

#### OVERSEAS MARKETING TEAM

3884-1 MINAMINOWA, KAMINA, NAGANO-PREF, 389-4588, JAPAN TEL : +81-(0)265-76-7751 FAX : +81-(0)265-76-3305 E-mail : intl@pisco.co.jp